

### **Clarification Request**

**Request from:** BTL Manager ([btl-manager@bacnetinternational.org](mailto:btl-manager@bacnetinternational.org))

**Reference:** "BTL Implementers Guide-17", "BTL Checklist-3.0.final", "ASHRAE 135.1-2003"

**Background:**

The property 'protocol-conformance-class' was deleted in protocol revision 2.

**Question:**

If a device supports a protocol revision of 2 or greater, should this property be required to be deleted (missing) from the device implementation?

**Response:**

Yes.