Clarification Request

References: <u>135.1.2013 7.3.2.X37.1.6</u>

Date of BTL-WG Response: 19-December-2019

☒All Actions Necessitated have been Completed

Background:

Problem:

The Accumulator object's Out_Of_Service test tests the Pulse_Rate property in step 6:

6. REPEAT X = (all values meeting the functional range requirements of 7.2.1) DO {
     WRITE Pulse_Rate = X
     VERIFY Pulse_Rate = X
    }

The Pulse_Rate property is optional so the test cannot be applied as written.

Question:

Should step 6 be skipped when the object does not support the Pulse_Rate property.

Response:

YES