Clarification Request

References: BTL Test Plan-16.1

Date of BTL-WG Response: **25-June-2020**

☒All Actions Necessitated have been Completed

Background: As per clause **18.2 of ANSI-ASHRAE Standard 135-2016 one of the error code is defined is related to UNSUPPORTED_OBJECT_TYPE but same is not defined for the error codes defined for Read Property Service clause 15.2 and Read Property Services Multiple clause 15.7**

Problem:

If Read property request is transmitted to the IUT for the object which is not supported (bit for respective object is FALSE in POTS property of device object) then IUT is responding with BACnet-Error PDU as:
Error Class = OBJECT,
Error Code = UNSUPPORTED_OBJECT_TYPE

Question:
1. **Is this error code (UNSUPPORTED_OBJECT_TYPE) acceptable since, it is not defined under error codes of documented under the Read Property Service section of manual.**

Response:

1. **No. Test 9.18.2.3 should fail.**