

Clarification Request

References: ASHRAE 135-2008, 135-2008v-2

Date of BTL-WG Response: June 3, 2021

Background:

Addendum 135-2008v-2

12.11.14 Protocol_Services_Supported

This property, of type BACnetServicesSupported, indicates which standardized protocol services are ~~supported~~ *executed* by this device's protocol implementation.

Question:

I think we can fix this issue by changing the EPICS. As we talked before, we do support 'ReinitializeDevice' service, but we do not want to expose it to external user, that's same with our previous products, so in our previous products, we all list 'F' in protocol-services-supported property, I should list 'F' in our EPICS. Please let me know whether you agree with that. Please help us to confirm that, that is important to us, because we were always hiding this service, expose it will make this controller different. We think hiding services or objects doesn't violate the standard. Lots of controllers do that.

Response:

No.