

Clarification Request

References: BTL Test Plan 12.0. section 3.13.2 reference to test 7.3.1.1

Date of BTL-WG Response: January 7, 2016

☒ All actions necessitated have been completed

Background:

In Addendum 135-2010ad-6 the requirements for the loop object were changed. Prior to protocol revision 13 the loop object present value had not been required to be writable when the property OutOfService had the value TRUE.

But chapter 3.13.2 Supports Writable Out_Of_Service Properties has long required to execute test 7.3.1.1 regardless of the protocol revision of the IUT. Test 7.3.1.1 will fail if the Present_Value does not become writable.

Proposal:

Change the Test Conditionality and append a sentence to Configuration Requirements:

If the IUT claims Protocol_Revision < 13 and the Present_Value of the Loop object is not writable when Out_Of_Service is TRUE, then the test shall be skipped.

As an alternative the test could be changed to not check the writability of the present value for that case.

Question:

Shall the conditionality be changed as proposed?

Response:

Yes, the Test Conditionality will be changed, and that sentence added to Configuration Requirements.