

Clarification Request

References: BTL testplan 5.0.final BTL specified test 7.3.2.24.x2

Background / Proposed Solution:

Test Configuration: The Trend Log is configured to acquire data by whatever means available. The Log_Buffer should be cleared, such that the **Record_Count is 0**. Configure the logging such that the entire test may be run without the trend buffer overflowing.

Problem #1: Normally "Configuration requirements" is used to introduce the IUt preparation, here "Test Configuration" is used, -> strange.

Problem #2: The Log_Buffer never equals zero when purged. The sentence is not necessary at all, this is performed in the first test steps. It looks as if this is a former part of the test concept or something.

Proposal:

Rewrite the Configuration requirements.

Proposal:

Configuration requirements: The Trend Log is configured to acquire data by whatever means available. Configure the logging such that the entire test may be run without the trend buffer overflowing.

Response:

Yes, the test configuration will be so clarified.